# **INFORMATION BULLETIN**



**INFORMATION BULLETIN:** 

#MWA016

**DATE:** 16/06/2017

AFFECTED DISCIPLINE:

All Disciplines

INFORMATION PERTAINS TO:

Machinery on Track

## DETAILS:

In the past few years, there has been reported incidents involving machinery on track, that is, whilst riders are participating.

These incidents have resulted in one case a fatality, and in another case serious injury, reports also have been received of several near misses.

# The risks are obvious and unnecessary.

Please be advised that while there are ANY riders on a hot track that under NO circumstances should any machines enter on, crossover or in any way travel on the race surface. This includes all level of events, competition recreation practise and coaching.

This includes but is not limited to

- Earth moving machinery
- Track maintenance machinery
- Water trucks or apparatus
- Personal transport such as quads mules and the likes
- Vehicles transporting officials, volunteers or riders.

## There is no situation that requires a vehicle to enter a hot track

First aid vehicles including ambulance, first intervention vehicles are not permitted, unless there is a strict written access protocol in place and under direct supervision of the Clerk of Course or their delegated authority.

Should your current club operations be resulting in vehicles entering a hot track whilst motorcycles are still participating, I would advise that your club operations need to be revised.

Pedestrian access has, and still is, permitted under the strict direction of the Clerk of Course or their delegated authority.

#### **EFFECTIVE FROM:**

IMMEDIATELY



25/168 Guildford Road, Maylands (Enter from 7th Av) PO Box 475, Maylands WA 6931 – PH: 08 9371 5333 – EMAIL: mail@motorcyclingwa.org.au